

Model: AP-C2.5 LCIT (RT3110)		Date: 29-Mar-11	No.: RD538001
Subject: Left Tray		Prepared by: N.Yoshida	
From: 1st Overseas Tech Support Sec., 1st PQM Dept.			
Classification:	<input type="checkbox"/> Troubleshooting	<input checked="" type="checkbox"/> Part information	<input type="checkbox"/> Action required
	<input type="checkbox"/> Mechanical	<input type="checkbox"/> Electrical	<input type="checkbox"/> Service manual revision
	<input type="checkbox"/> Paper path	<input type="checkbox"/> Transmit/receive	<input type="checkbox"/> Retrofit information
	<input type="checkbox"/> Product Safety	<input type="checkbox"/> Other ()	<input type="checkbox"/> Tier 2

Change/Reason: The following was added as a service part.

New part number	Description	Q'ty	Int	Page	Index	Note
B8012722	TANDEM TRAY:LEFT	1		7	32	

Change/Reason:

