

RICOH**Part Change Information List**

Date: March 31, 2011

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
AP-C2.5 LCIT (RT3010)	D539	201103		D5395100	D5395110	PCB:BANK:SIDE LCT	1	1	X/O		9	5					V1100077	10110378

RICOH**Part Change Information List**

Date: April 28, 2011

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
AP-C2.5 LCIT (RT3010)	D539	201104		D5395100	D5395110	PCB:BANK:SIDE LCT	1	1	X/O		15	5					V1100077	10110378



RICOH**Part Change Information List**

Date: December 28, 2011

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
AP-C2.5 LCIT (RT3010)	D539	201112		D3531023	D6312023	SHAFT:FEED:ASS'Y	1	1	X/O		9	26					V1103271	11110188
AP-C2.5 LCIT (RT3010)	D539	201112			D5391255	PROTECTION:COUPLING:SWITCH	0	1			11	21	A		Y		V1103284	11110052
AP-C2.5 LCIT (RT3010)	D539	201112			04543010G	TAPPING SCREW:3X10	0	1			11	107	A		Y		V1103284	11110052

RICOH**Part Change Information List**

Date: August 31, 2012

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Qty	New Qty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
AP-C2.5 LCIT (RT3010)	D539	201208		D3533860	M4223860	BRACKET-COUPLING:REAR:PEEN	1	1	X/O		3	22					V1201849	12071400