



Part Change Information List

Date: April 28, 2011

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
AP-C2.5 LCIT (RT3110)	D538	201103			B8012722	TANDEM TRAY:LEFT	0	1			7	32			RD538001		V1100379	



Part Change Information List

Date: April 28, 2011

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
AP-C2.5 LCIT (PB3110)	D538	201104		D5385100	D5385110	PCB:BANK:LCT	1	1	X/O		15	5					V1100077	10110378

RICOH**Part Change Information List**

Date: August 31, 2011

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
AP-C2.5 LCIT (PB3110)	D538	201108		D5385110	D5385120	PCB:BANK:CEBU-C:ASS'Y	1	1	X/O		15	5					V1101069	11050758



Part Change Information List

Date: February 28, 2014

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Int	RTB	Note	Ref Number	ECN Number
AP-C2.5 LCIT (PB3110)	D538	201402		D5375300	D7465300	HARNESS:INTERFACE:UPPER:ASSY	1	1	O/O		5	6					V1300315	13011484



Part Change Information List

Date: June 30, 2014

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
AP-C2.5 LCIT (PB3110)	D538	201406		B8015311	D7475311	HARNESS:CEBU:TANDEM TRAY:ASS'Y	1	1	O/O		7	5					V1300315	13011484

RICOH**Part Change Information List**

Date: July 31, 2014

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Qty	New Qty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
AP-C2.5 LCIT (PB3110)	D538	201407		D5385340	D7475340	HARNESS:PAPER VOLUME SENSOR:ASSY	1	1	O/O		15	15					V1300315	13011484

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Qty	New Qty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
AP-C2.5 LCIT (PB3110)	D538	201410		D5385350	D7475350	HARNESS:LIFT MOTOR:ASSY	1	1	O/O		15	17					V1300315	13011484



Part Change Information List

Date: February 1, 2016

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
AP-C2.5 LCIT_PB3110_	D538	201601		AA043599	AA043714	TIMING BELT:60S3M588	1	1	O/O	Y							V1502639	15090525



Part Change Information List

Date: May 12, 2017

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
AP-C2.5 LCIT_PB3110_	D538	201704		D5385320	D7475320	HARNESS.MOTOR:ASSY	1	1	O/O	Y							V1300315	13011484