



Part Change Information List

Date: April 30, 2009

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number
PU3000 Punch Unit	B807	200904		B8072110	B8072111	PUNCH UNIT:NA:ASS'Y	1	1	X/O		5	11	X/O			For NA model	
PU3000 Punch Unit	B807	200904		B8073110	B8073111	PUNCH UNIT:EU:ASS'Y	1	1	X/O		5	11	X/O			For EU model	
PU3000 Punch Unit	B807	200904		B8074110	B8074111	PUNCH UNIT:NORTH EU:ASS'Y	1	1	X/O		5	11	X/O			For North EU model	

RICOH**Part Change Information List**

Date: December 28, 2011

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
Punch Unit PU3000	B807	201112		A6061885	A8127885	DECAL:TONER HOPPER	1	1	X/O		3	17					V1102537	11091186
Punch Unit PU3000	B807	201112		B8045302	B8045393	HARNESS:PUNCH UNIT:REGISTRATION SENSOR:MOTOR	1	1	O/O		5	14					V0701652	06111080

RICOH**Part Change Information List**

Date: July 31, 2012

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Qty	New Qty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
PU3000 Punch Unit	B807	201207		B7025305	B8075405	HARNESS:REGISTRATION SENSOR:SIDE	1	1	X/O		3	9					V1200760	12021385